

P3 High Street Terang Electrical Incident

17 March 2018

Technical investigation report

Preface

This technical investigation report has been prepared by Energy Safe Victoria (ESV) pursuant to the objectives, powers and functions conferred on it by The Electricity Safety Act 1998 (Act).

Specifically, these include, amongst other things, to investigate events or incidents, which have implications for electricity safety and to regulate, monitor and enforce the prevention and mitigation of bushfires that arise out of incidents involving electric lines or electrical installations and to monitor and enforce compliance with this Act and the regulations.

Contents

- Summary5**
 - Report structure.....6

- Introduction.....7**
 - Scope7
 - Objectives7
 - Methodology8
 - Background8
 - Declarations.....10
 - Investigation sequence of events12
 - Site plan.....12

- Technical investigation.....14**
 - Site plan post-event.....14
 - Asset evidence15
 - Asset information.....19
 - Network asset inspections.....21
 - Operations records.....22
 - Prevailing weather information23

- Findings and conclusions25**
 - The source of the Terang-Cobden Road fire25
 - Circuit breaker operations25
 - Conductor clearances25
 - Construction to standards25
 - The network asset inspection process26

- Appendix A – Weather Observations27**

Figures

Figure 1: the Terang-Cobden Road fire ignition incident location	9
Figure 2: the extent of the Terang-Cobden Road fire (burnt land)	9
Figure 3: upper and lower P3 22kV circuit layouts	10
Figure 4: GIS incident site area map	10
Figure 5: the TRG Central 22kV electrical system diagram and incident location	11
Figure 6: site plan pre-event	13
Figure 7: site plan post-event	15
Figure 8: video stills showing the range of conductor movement (horizontal and vertical).....	16
Figure 9: P3 22kV conductor clash damage (position 1, 2 and 3)	16
Figure 10: clearances between the upper and lower P3 22kV conductors	18
Figure 11: existing crossarm condition	19
Figure 12: conductor clearances recorded on 19 March 2018 before and after repair.....	20
Figure 13: Terang 004 feeder protection equipment operation information	23
Figure 14: excerpt from the Warrnambool weather record for March 2018	23
Figure 15: excerpt from the Mortlake weather record for March 2018.....	23

Summary

On 17 March 2018, at approximately 20:49 Australian Eastern Standard Time¹ (AEST), a high wind event passing through Victoria's South West Region caused a fault on the electrical network and a fire in the Terang area that resulted in significant property damage.

The fire originated at or close to the location of Pole 3 (P3) on Powercor Australia Limited's distribution network on the 22 kilovolt (kV) Terang 004 feeder (TRG 004), which attaches to a pole line that also carries the Terang to Warrnambool No.2 66kV line, near the intersection of Peterborough Road and High Street, Terang.

Energy Safe Victoria's (ESV) technical investigation has established the following:

- there was evidence of arcing damage to the P3 22kV overhead conductors
- on 17 March 2018
 - the closest weather stations to the ignition site recorded north-westerly wind gusts of up to 104 kilometres per hour at or around 20:00 AEST
 - four short circuit events occurred on the TRG 004 line between 20:45 and 20:49 AEST. These short circuit events collectively involved all three electrical phases, which is consistent with the damage to the P3 22kV conductors
 - the TRG 004 circuit breaker operated four times to clear the four short circuit events
 - on a Code Red day the TRG 004 circuit breaker would have operated for the first short circuit event and locked out
- the electrical clearances (distances) between the:
 - upper and lower P3 22kV conductors were not constructed to Australian Standard (AS/NZS 7000:2016) or the Powercor Australia Limited Distribution Construction Standard (DC161)
 - 22kV conductors and the ground were not constructed to the Australian Standard (AS/NZS 7000:2016) or the Powercor Australia Limited Technical Standard (DC111)
- Powercor Australia Limited has records of inspection involving P3 and other network assets in the vicinity and no instances of out-of-specification conductor or ground clearances were noted
- The Powercor asset management plan requires inspectors to check for non-compliant ground clearance and "out of sag" conductors
- The asset management plan² refers to a survey to be undertaken to establish and record the spatial relationship between conductors and conduct engineering design checks
- Powercor Australia Limited records show that the last work performed on P3 (to replace its lower crossarm) occurred in December 2009.

¹ All time references in this report refer to Australian Eastern Standard Time

² Powercor Australia Ltd Asset Management Plan (PAL-AMP-07), section 6.4.3. 23/02/2015. Iss.3.0.

As a result of its investigations, ESV has concluded that:

- the Terang-Cobden Road fire's most likely source of ignition was molten conductor material falling from clashing and arcing conductors at or around 20:49 AEST, and the damage to the conductors is consistent with this conclusion
- on 17 March 2018, the clearances between the upper and lower P3 22kV conductors were not sufficient to prevent arcing from clashing conductors during the high wind event
- the TRG 004 circuit breaker operated as expected with the TFB protection settings as applied.

ESV will now undertake a formal legal review to determine the nature and extent of any breaches to the Act and regulations, ESV Directions and the nature of any consequential enforcement action.

Report structure

In this report, the:

- introduction provides information about: the investigation's scope, objectives, and methodology; the time, condition, and origins of the Terang-Cobden Road fire; the prevailing declarations at the time of the incident (which involved a Total Fire Ban, a Hazardous Bushfire Risk Area, and Powercor Australia Limited special protection settings for Total Fire Ban days); the investigation's sequence of events; and a plan of the incident site
- technical investigation section provides information about the site after the incident, the results of ESV's analysis of the evidence, information about the assets involved and their associated inspections, and the network operations records and prevailing weather at the time of the incident
- findings and conclusions section summarises the technical investigation's key findings, which involve the source of the Terang-Cobden Road fire, conductor clearances, specifications in standards, and the network asset inspection process.

Introduction

Scope

This report details the findings of an Energy Safe Victoria (ESV) technical investigation of the causes of, and contributing factors to, the Terang-Cobden Road fire that originated at or near the Terang Zone Sub-Station (TRG ZSS) on 17 March 2018.

The investigation only details the evidence gathered to support the technical conclusion reached as well as outlining the relevant standards, plans or procedures that apply to the distribution network at this location.

Objectives

ESV's investigative objectives involved:

- identifying the entities involved
- establishing the initial facts and possible causes of the incident
- identifying any relevant standards and work practices that may have been a factor.

To meet these objectives, ESV sourced specific information that included:

- Bureau of Meteorology (BOM) and Emergency Management Victoria (EMV) data from weather stations³ closest to the ignition source
- Terang 004 feeder (TRG 004) protection equipment operation records
- Powercor Australia Limited's:
 - incident report
 - protection equipment operation records
 - Distribution Construction Standard (DC161)
 - Technical Standard (DC111)
 - Asset Management Plan
 - Asset Inspection Manual.
- a summary of the line inspection data for Pole Three (P3) and Anchor P3
- construction information from the relevant detailed route plans (DRPs)
- clearance distances recorded by Powercor Australia Limited before and after site rectification and repair works.

ESV also used Section 134 of the Electrical Safety Act 1998 (Power of enforcement officer to require information or documents for the purpose of investigating a serious electrical incident) to require the provision of certain information.

³ Warrnambool and Mortlake

Methodology

ESV's investigative methodology involved a combination of practices, procedures, and processes that involved:

- requiring and analysing specific information from Powercor Australia Limited
- reviewing and analysing TRG 004 feeder protection equipment operation records
- reviewing weather records from the closest BOM weather stations
- reviewing weather records and seek any expert opinion from Emergency Management Victoria (EMV) on the nature of the weather event
- inspecting damaged pieces of 22 kilovolt (kV) conductor recovered from conductors connected to P3
- reviewing photos taken at the site on the day following the incident
- reviewing other reports and information as provided by Powercor Australia Limited and the Country Fire Authority (CFA).

Background

On 17 March 2018, at approximately 20:49 Australian Eastern Standard Time (AEST), a high wind event passing through Victoria's South West Region caused a fault on the electrical network and a fire in the Terang area that resulted in the destruction of eighteen homes and forty-five sheds. There were no fatalities or serious injuries.

The fire originated at or close to the location of Pole 3 (P3) on Powercor Australia Limited's distribution network on the 22 kilovolt (kV) Terang (TRG) 004 feeder (TRG 004), which attaches to a pole line that also carries the Terang to Warrnambool No.2 66kV line⁴, at the location of Pole 3 (P3) near the intersection of Peterborough Road and High Street, Terang. The network assets involved were:

- P3, which is a 'Tee-On' structure (see Fig 3) located on the south side of High Street⁵
- Anchor P3, which is an anchor pole located on the north side of High Street.

On 18 March 2018, Victoria Police fire investigators requested ESV's attendance at the incident site near TRG ZSS and P3.

Figure 1 and Figure 2 show aerial views of the incident location of the Terang-Cobden Road fire and the extent of the damage (respectively). Figure 3 shows a diagram of P3 and the arrangement of its upper and lower circuits, which are both 22kV. P3 also carries the Terang to Warrnambool No.2 66kV line in parallel from a crossarm at the top of P3, however there is ample clearance between the lower 22kV and the higher 66kV conductors and there was no evidence to indicate the 66kV line in any way contributed to, or was involved in the incident. This is not shown on the diagram and does not otherwise factor in the investigation.

⁴ This line runs in parallel above TRG 004.

⁵ P3 (LIS # 409916) has a lower 22kV circuit that attaches to an upper 22kV circuit that crosses the Princess Highway to the high voltage anchor pole (LIS # 408500).

Figure 1: the Terang-Cobden Road fire ignition incident location





Figure 2: the extent of the Terang-Cobden Road fire (burnt land)



Figure 3: upper and lower P3 22kV circuit layouts



Declarations

The declarations relating to the period of the incident involved a Total Fire Ban (TFB) day, a Hazardous Bushfire Risk Area (HBRA), and Powercor Australia Limited special protection settings for TFB days.

Total Fire Ban day

On 17 and 18 March 2018, TFB days were in place for the Southwest Fire District, which includes the Terang area⁶.

Hazardous Bushfire Risk Area

Figure 4 shows a Graphical Information System (GIS) area map of the incident site in relation to the CFA declared Low Bushfire Risk Area (in green) and the HBRA area (in amber).

Figure 4: GIS incident site area map



⁶ Country Fire Authority 2018, State Government of Victoria, Melbourne, viewed 7 May 2018, www.cfa.vic.gov.au/warnings-restrictions/history-of-tfbs.

Powercor Australia Limited special protection settings


Powercor Australia Limited has an accepted (by ESV) bushfire management plan (including any actions required) for managing risk on TFB days. The plan, which considers a number of factors including environmental, involves initiating special protection (suppression) settings for identified assets:

- The TRG 004 feeder circuit breaker is an identified asset to which TFB day settings should be applied⁷
- The TRG 004 feeder circuit breaker protection settings were logged as suppressed on 17 March 2018 at 11:10 AEST and restored on 18 March 2018 at 00:33 AEST⁸. This terminology means that the protection was set to operate more quickly (i.e. the fast overcurrent setting)

Figure 5 shows a section of the TRG Central 22kV electrical network diagram and the:

- network assets in the Terang area
- TRG 004 feeder (in green)
- incident location.

Figure 5: the TRG Central 22kV electrical system diagram and incident location



⁷ Powercor Australia Limited, Total Fire Ban Action Plan, Attachment A, 2018.

⁸ Powercor Australia Limited, Station Log Files, 17 and 18 March 2018.

Investigation sequence of events

On 18 March 2018:

- Victoria Police requested ESV's attendance at the incident site to help identify the cause of ignition near the TRG ZSS
- ESV dispatched an enforcement officer at 15:20 AEST to the incident site to meet with the Powercor Australia Limited Network Availability Officer and representatives from Victoria Police
- the Powercor Australia Limited Network Availability Officer showed a video of the span of conductors involved in the incident. The video was taken on 18 March 2018 at approximately 11:40 AEST
- the ESV enforcement officer took pictures of the P3 electrical conductors showing arcing damage
 - measured the height of the conductor span⁹ that crosses the Princess Highway.

On 19 March 2018, ESV's Head of Regulatory Assurance produced the South West Fires Summary Update for ESV Senior Management¹⁰.

On 28 March 2018, ESV's formal technical investigation was approved by the General Manager, Electrical Safety and Technical Regulation.

On 3 April 2018, ESV required Powercor Australia Limited to supply relevant documents and information under Section 134 of the Electrical Safety Act 1998.

On 10 April 2018, Powercor Australia Limited responded by providing the relevant documents and other information requested by ESV.

On 13 April 2018, ESV attended the incident site to collect more information relating to the electrical assets.

Site plan


Figure 6 shows a plan of the incident location prior to the incident that includes the:

- Terang Zone Substation (TRG ZSS)
- P3 and Anchor P3 (and their corresponding unique line information system (LIS) numbers) in relation to High Street (Princess Highway)
- the distance of the span crossing High Street
- way the three conductors were bridged (joined) at P3 (indicated by the symbols R W B; see Figure 10 for more information about the Red, White and Blue Phases).

⁹ The Suparule Cable Height Meter measures cable sag, cable height, and overhead clearance. For more information see <http://www.suparule.com/products/cable-height-meter/>.

¹⁰ Fox, B, Head of Regulatory Assurance, South West Fires Summary Update, March 2018, Energy Safe Victoria, State Government of Victoria, Melbourne.

Figure 6: site plan pre-event



Technical investigation

ESV's technical investigation has involved:


- mapping the incident site after the event
- inspecting asset evidence, including video evidence, photographic evidence, and the damaged conductor sections
- collecting and reviewing relevant asset information, including P3's construction history, the relevant standards applying to network asset maintenance, and P3's records of repair
- reviewing the records of inspection for the network assets involved
- reviewing the TRG 004 feeder protection equipment operation records
- studying prevailing weather information from the Bureau of Meteorology and Emergency Management Victoria.

Site plan post-event

Figure 7 shows details of the incident location that includes the:

- prevailing wind direction
- burnt area directly beneath P3 (in grey)
- location of the conductor clash relative to TRG ZSS and High Street (Princess Highway)
- location of ground clearance measurements and the distance measured between the ground and the conductor span crossing High Street prior to the removal of the damaged conductors and the start of restoration work.

Figure 7: site plan post-event



Asset evidence

Video analysis

On 18 March 2018, following identification of the fault location, Powercor Australia Limited recorded a video of the site at approximately 11:40 AEST¹¹. The video shows the:

- possible range of movement of the conductors due to gusting winds (up to 96 kilometres per hour recorded at the Warrnambool Weather Station at 11:15 AEST, and 76 kilometres per hour recorded at the Mortlake Weather Station at 11:28 AEST)
- changes in clearance between the upper and lower conductors.

Figure 8 shows a series of stills from the video. In the stills, the yellow arrows indicate horizontal movement (swing) and the red arrows indicate vertical movement. The movement is caused by gusting winds that cause the conductors to move vertically and horizontally at the same time, with the possible range of movement being directly proportional to the amount of sag in the conductor (the greater the sag, the greater the movement).

¹¹ Provided to the ESV enforcement officer on 19 March 2018 at 13:30 AEST.


Figure 8: video stills showing the range of conductor movement (horizontal and vertical)



Photographic analysis

Figure 9 shows a series of pictures of the P3 22kV conductor clash damage taken by ESV's enforcement officer on 18 March 2018 (at approximately 17:40 AEST).


Figure 9: P3 22kV conductor clash damage (position 1, 2 and 3)



Position 1



Position 2




Position 3

White Phase conductor lower circuit (pit marks)

Figure 10 shows the layout of the upper and lower P3 22kV conductors, and identifies the Red, White (shown in black) and Blue Phase conductors. It also shows the reduced clearances between the Red Phase upper and Blue Phase lower conductors.

Figure 10: clearances between the upper and lower P3 22kV conductors



From the pictures it was observed that:

- there was arcing damage to the:
 - upper circuit Red Phase conductor
 - lower circuit Blue Phase and White Phase conductors
- the lower circuit White Phase conductor featured arcing damage likely to have been caused by the arcing of all three phases (see Figure 13 and the three-phase TRG 004 events 2 and 3 for more information; it is also likely that the Blue and Red Phase arcing event created another arc that was blown towards the White Phase conductor, resulting in the two three-phase events)
- damage was limited to the conductors on P3's north-east side.

Damaged conductor analysis

On 26 March 2018, the CFA provided ESV with sections removed from the P3 conductors that included the upper (north-south) circuit Red Phase (the 'Tee-On' conductor) and the lower (east-west) circuit Blue Phase (the straight through conductor). The conductors show evidence of more than one arcing event, with the:

- upper circuit Red Phase conductor showing localised damage to a 250 millimetre section
- lower circuit Blue Phase conductor showing damage to a longer, 510 millimetre section, which can be explained by the extent of the Red Phase conductor's horizontal movement and the multiple contact points.

Each conductor comprises multiple strands and strand sections were missing from both. This indicates either melting or breakage of the strands due to the effect of arcing from the short-circuit events.

Asset information

P3 construction history

Powercor Australia Limited provided ESV with detailed route plans (DRP) of the area around P3 dating back to 1976. The DRPs:

- record the designs and act as the area's as-built record
- explain the structure types and refer to relevant construction standards
- are updated when new construction work requires an asset design change.

DRPs do not record like-for-like replacement under maintenance.


The most recent plan indicates design and construction changes up to March 2008, while historical details include the following:

- the original construction design required aluminium conductor steel reinforced (ACSR) 'Tee-On' conductors to be tensioned to an all-aluminium conductor stringing chart.
- one of the P3 22kV circuits is not as described by the DRP (being a 6/1/.144 ACSR type and not the 6/.186 ACSR type as described).
- P3 was constructed to an old State Electricity Commission of Victoria (SECV) drawing and originally featured wooden crossarms. Both crossarms have since been changed, with the lower crossarm replaced in December 2009.

Figure 11 shows the existing P3 22kV crossarms and their condition. From the figure it can be observed that:

- the upper crossarm has been replaced (the date of replacement cannot be verified)
- an old crossarm hole suggests the current upper crossarm has been moved higher up the pole, increasing the clearance between the upper and lower conductors¹²
- the distance between crossarms is approximately 1.4 metres
- two glass insulator discs were left attached to the centre phase upper circuit.

Figure 11: existing crossarm condition



¹² It is unknown whether the outside conductors were shortened and re-terminated to manage the sag due to the extra length of the newer style polymeric strain insulators. (the newer style insulators are approximately 280 millimetres longer than the glass disc insulators previously used on wooden crossarms carrying 22kV circuits)

Relevant standards

The current standards relevant to these network assets and the circumstances of the event involve:

- phase-to-phase clearances specified by the
 - Overhead Line Design Standard AS/NZS 7000:2016
 - Powercor Australia Limited Distribution Construction Standard (DC161)
- conductor-to-road/ground clearances specified by the
 - Overhead Line Design Standard AS/NZS 7000:2016
 - Powercor Australia Limited Technical Standard (DC111).

The above Powercor standards were applicable in December 2009 when P3 was last maintained. AS/NZS 7000 was first released in 2010, its predecessor (which AS/NZS 7000 was based on) was industry guideline Energy Networks Australia (ENA) C(b)1 2006. The relevant requirements of both are the same.

Legacy SECV standards applicable to the initial construction in the 1970's were not considered relevant to the investigation.

Repairs


On 19 March 2018, Powercor Australia Limited crews completed repairs that included:

- replacing the damaged conductor sections
- straightening Anchor P3.

ESV requested that measurements be taken of the conductor phase-to-phase clearances between the upper and lower P3 conductors before and after the repairs.

Figure 12 shows a diagram (the original of which was provided by Powercor Australia Limited¹³) that details the conductor clearances recorded on 19 March 2018 before and after repairs. The completed repairs were not constructed to the relevant standards.

Figure 12: conductor clearances recorded on 19 March 2018 before and after repair



¹³ Coverdale, J, Construction Project Leader, March 2018, Powercor Australia Limited, Melbourne.

Phase-to-phase clearance standards

The phase-to-phase clearances measured by Powercor Australia Limited between the upper and lower 22kV conductors (ranging from 210 millimetres¹⁴ to 810 millimetres before repair) were all less than the 900 millimetre phase-to-phase clearance specified by the:

- Overhead Line Design Standard AS/NZS 7000:2016
- Powercor Australia Limited Distribution Construction Standard (DC161).

Conductor-to-road/ground clearance standards

- The conductor-to-road/ground clearances measured by Powercor Australia Limited ranged from 5,900 millimetres to 6,420 millimetres before repair. The Overhead Line Design Standard AS/NZS 7000:2016 and the Powercor Australia Limited Technical Standard (DC111) specify a minimum clearance of 6900 millimetres.

Following repairs, the conductor-to-road clearance of one conductor did not meet this standard.

Network asset inspections

Powercor Australia Limited has contracted out its network asset inspection services to Electrix Pty Ltd for more than ten years. Under this agreement, Electrix Pty Ltd inspectors record site inspection information, which is transferred to Powercor Australia Limited's maintenance section.

Over the last ten years, Electrix Pty Ltd inspected¹⁵:

- P3 four times (on 17 January 2007, 21 December 2011, 7 July 2014, and 3 January 2017)
- Anchor P3 three times (on 17 February 2012, 3 September 2014, and 9 February 2017).

The records provided show no evidence of reduced clearances being logged as a defect, and it is unknown exactly when (or how) the reduced conductor clearances occurred.

Documents that are relevant to the network asset inspection process include the Powercor Australia Limited Asset Management Plan and Asset Inspection Manual.

Asset Management Plan

The Asset Management Plan for overhead conductors provides the following information¹⁶:

Section 3.3, Asset Condition and Age Profile, states:

“Where multiple circuits are supported by the same poles there is further need to ensure that conductors are in serviceable condition and lines appropriately designed to mitigate the likelihood of circuit to circuit contact.”

Section 3.6, Condition Monitoring, states:

“Overhead conductors are inspected during the normal inspection processes as mentioned below.

- *Pole inspection - visual survey with focus on the conductor condition at the pole top.*

Conductors that exhibit visible signs of mechanical degradation like corrosion, out of sag, caging broken strands, vibration damage and other defects are identified during the above inspection processes”

¹⁴ The clearance between the Red Phase to Blue Phase conductors that clashed and arced.

¹⁵ Powercor Australia Limited information system.

¹⁶ Powercor Australia Limited, Asset Management Plan, Document No. 01-00-M0015 (PAL-AMP-07), Issue 3.0, 23 February 2015, p. 12, 14, 27.

Section 6.4.3, Interpretation, states:

“...continue the current practice of asset inspectors checking for non-compliant ground clearance and “out of sag” conductors in single circuit bare open wire power lines in the cyclic inspection program. These instances are reported and actioned in accordance with the Network Asset Maintenance Priority Policy (Document No 05-C001.A – 025).”

The asset inspection records show no evidence that visible signs of degradation, non-compliant ground clearance or incorrectly sagged conductors were identified when P3 and Anchor P3 were inspected.

The Powercor asset management plan¹⁷ states that it “will assess all spans of multi circuit high voltage bare open wire conductor for compliance with the requirements of ENA C(b)1 Section 10.3 “Guidelines for Design and Maintenance of Overhead Transmission and Distribution lines; this assessment will require a greater standard of data acquisition and analysis than is available in the cyclic asset inspection programme and so will be subject to a separate programme of special survey to establish and record the spatial relationship of conductors and conduct engineering design checks that will be designed to be completed in time to enable any required re-construction works or fitting of spacers (spreaders) to be completed by the time frames stated in part f of the direction i.e. 1 Nov 2016 for HBRA and 1 Nov 2020 for LBRA.”

Asset Inspection Manual

The Asset Inspection Manual work instruction¹⁸:

- states that aerial line ground clearances are to be inspected as part of cyclic and non-cyclic inspection programs
- details the required definitions for (and expectations from) assessment tasks and how they are to be reported.

No records have been found of ground clearance measurements being taken at the incident site or of any defects being raised.

Operations records

The protection settings on the TRG004 circuit breaker located at TRG ZSS were set to cause the circuit breaker to operate in a shorter than normal time (i.e. fast overcurrent) at the time of the incident.

Figure 13 shows an excerpt from Powercor Australia Limited’s TRG 004 feeder protection equipment operation information. The excerpt indicates that on 17 March 2018 there were four short circuit events between 20:45 and 20:49 AEST:

- two events (No. 4 and 5) included the Red and Blue Phase conductors (phase-to-phase).
- two events (No. 2 and 3) included the Red, White and Blue Phase conductors (three phase).

These events collectively identify all three conductor phases as being involved in the events, which is consistent with the visual damage observed to the three conductors at P3.

¹⁷ Powercor Australia Ltd Asset Management Plan (PAL-AMP-07), section 6.4.3. 23/02/2015. Iss.3.0.

¹⁸ Powercor Australia Limited, Asset Inspection Manual, Work Instruction for Inspection of Aerial Line Ground Clearances, Section G.4-WI.

Figure 13: Terang 004 feeder protection equipment operation information

TRG004				
No.	Time (AEST) (+11)	Type	Magnitude @ Trip	Reclose
5	20:45:32.172	Red to Blue (Ph-Ph)	3.8kA	Yes
4	20:47:09.309	Red to Blue (Ph-Ph)	3.8kA	Yes
3	20:48:41.818	Red/White/Blue (3P)	4.4kA	Yes
2	20:49:12.939	Red/White/Blue (3P)	4.3kA	No – within reclaim time
1	-	Manual Open Command	-	-

Had the protection been set not to reclose (as would have been the case on a Code Red Day) the circuit breaker would only have operated once (event No. 5) and then locked open until the line had been inspected.

Prevailing weather information

Bureau of Meteorology Information

Warrnambool and Mortlake are the closest weather stations to the incident site. Prevailing weather information on the day has been sourced from the Bureau of Meteorology (BOM) website¹⁹.

Figure 14 shows an excerpt from the Warrnambool Weather Station records, which indicates that on 17 March 2018 at 20:00 AEST, north westerly winds with a maximum gust of 104 kilometres per hour were recorded.

Figure 14: excerpt from the Warrnambool weather record for March 2018

Warrnambool, Victoria March 2018 Daily Weather Observations									
Date	Day	Temps		Rain mm	Evap mm	Sun hours	Max wind gust		
		Min °C	Max °C				Dirn	Spd km/h	Time local
16	Fr	5.9	23.7	0			NE	31	10:40
17	Sa	12.0	34.1	0.6			NW	104	20:00
18	Su	12.9	20.2	2.8			W	96	11:15
19	Mo	10.7	23.2	1.4			NW	65	13:08

See Appendix A for more information.

Figure 15 shows an excerpt from the Mortlake Weather Station records, which indicates that on the 17 March 2018 at 20:08 AEST, north westerly winds with a maximum gust of 104 kilometres per hour were recorded.

Figure 15: excerpt from the Mortlake weather record for March 2018

Mortlake, Victoria March 2018 Daily Weather Observations									
Date	Day	Temps		Rain mm	Evap mm	Sun hours	Max wind gust		
		Min °C	Max °C				Dirn	Spd km/h	Time local
16	Fr	5.5	26.4	0			WNW	35	13:26
17	Sa	10.7	34.0	0			NW	104	20:08
18	Su	12.5	21.1	0.4			WNW	76	11:28
19	Mo	9.1	23.5	0.2			W	57	12:36

See Appendix A for more information.

¹⁹ Bureau of Meteorology 2018, Australian Government, viewed 14 April 2018, www.bom.gov.au.

Emergency Management Victoria information

Emergency Management Victoria provided ESV with a more detailed weather record from the Mortlake Automatic Weather Station to establish whether the 17 March 2018 high wind event was unusual²⁰. The record covered the period from 09:00 AEST on 17 March 2018 to 08:30 AEST on 18 March 2018, and while it provided more information about the intensity of the wind and when wind conditions changed, it offered no evidence that the wind event was exceptional.

²⁰ State Control Centre (Intelligence Section), mortlake_aws_terang_fire.xlsx, viewed May 2018.

Findings and conclusions

ESV's findings and conclusions specifically relate to the source of the Terang-Cobden Road fire and the role played by the conductor clearances, the relevant conductor clearance standards, and the network asset inspection process.

The source of the Terang-Cobden Road fire

The most likely source of the Terang-Cobden Road fire on 17 March 2018 was molten material falling from clashing and arcing conductors near P3 at or around 20:49 AEST due to a high wind event, as evidenced by arcing damage to the three 22kV conductors.

Circuit breaker operations

The protection settings on the TRG004 circuit breaker located at TRG ZSS were set to cause the circuit breaker to operate in a shorter than normal (i.e. fast overcurrent) time at the time of the incident.

The circuit breaker operated four times with settings applied in accordance with the current approved Powercor Bushfire Mitigation Plan.

Had the protection been set not to reclose (as would have been the case on a Code Red Day) it would only have operated one.

Conductor clearances

On 17 March 2018, the clearances between the upper and lower P3 22kV conductors were insufficient to prevent clashing and arcing during the high wind event.

Construction to standards

The lines were not constructed to maintain the P3 22kV conductor clearances (both phase-to-phase and conductor-to-road/ground) as specified in the standard

Phase-to-phase clearance requirements are stated in the:

- Australian Overhead Line Design Standard AS/NZS 7000:2016
- Powercor Australia Limited Distribution Construction Standard DC161.

Both standards specify a 900 millimetre clearance. The clearances between the upper and lower 22kV conductors ranged from 210 millimetres to 810 millimetres.

Conductor-to-road/ground clearance requirements are stated in the:

- Australian Overhead Line Design Standard AS/NZS 7000:2016
- Powercor Australia Limited Technical Standard DC111.

Both standards specify a 6,900 millimetre clearance between the conductors and the road. The clearances ranged from 5,900 millimetres to 6,420 millimetres.

The network asset inspection process

Over the last 10 years:

- P3 was inspected four times (on 17 January 2007, 21 December 2011, 7 July 2014, and 3 January 2017)
- Anchor P3 was inspected three times (on 17 February 2012, 3 September 2014, and 9 February 2017).

There is no evidence from the inspection records that conductor clearances have been logged as a defect or that ground clearance measurements were taken.

Appendix A – Weather observations

Warrnambool, Victoria
March 2018 Daily Weather Observations



Date	Day	Temps		Rain	Evap	Sun	Max wind gust			Sam					3pm							
		Min °C	Max °C				mm	mm	hours	Dirn	Spd km/h	Time local	Temp °C	RH %	Cld eighths	Dirn	Spd km/h	MSLP hPa	Temp °C	RH %	Cld eighths	Dirn
1	Th	13.9	20.3	1.2			SSW	43	16:10	14.8	94		SW	15	1018.3	18.7	66		S	22	1018.4	
2	Fr	9.5	27.5	0.2			S	31	15:51	13.1	96		E	7	1015.7	26.1	34		ENE	9	1012.0	
3	Sa	11.7	22.8	0			SW	50	14:47	17.5	76		WNW	22	1008.7	20.2	64		SW	31	1010.7	
4	Su	8.6	20.1	0.2			SSW	41	13:07	16.5	70		SSW	7	1016.9	19.7	41		SSW	26	1017.2	
5	Mo	7.8	21.2	0			SSW	43	13:13	14.2	78		WNW	6	1020.4	19.0	44		S	28	1022.5	
6	Tu	11.0	22.2	0			S	54	13:27	16.5	67		SE	22	1026.3	20.3	58		SSE	37	1025.4	
7	We	8.8	26.9	0			SSE	35	17:45	15.3	89		ESE	7	1026.0	24.5	52		S	22	1023.8	
8	Th	9.2	28.8	0			S	33	14:53	17.1	75		NNE	15	1024.3	27.5	36		SSW	20	1022.9	
9	Fr	12.0	31.4	0			SSW	33	15:08	18.2	68		ENE	6	1025.2	30.1	31		SSW	19	1023.3	
10	Sa	12.8	36.6	0			NW	39	12:08	19.0	58		NNE	17	1023.3	35.8	13		W	13	1020.8	
11	Su	14.5	21.1	0			SSW	44	14:51	18.5	79		SSW	22	1024.2	19.0	59		SSW	30	1025.4	
12	Mo	14.7	19.9	0			SSW	44	15:18	15.8	69		SW	24	1024.8	18.8	56		SW	30	1024.0	
13	Tu	14.5	21.0	0			SSW	46	13:47	17.5	60		SSW	20	1024.5	19.0	50		SSW	26	1023.6	
14	We	12.9	20.6	0			SSW	37	12:24	16.2	64		S	13	1021.2	18.5	53		SSW	22	1018.6	
15	Th	8.1	20.1	0			SW	37	13:01	13.8	78		NNW	13	1015.4	17.9	70		WSW	26	1016.1	
16	Fr	5.9	23.7	0			NE	31	10:40	12.0	97		NNE	9	1016.3	23.3	41		NNW	15	1012.6	
17	Sa	12.0	34.1	0.6			NW	104	20:00	22.0	65		N	19	1009.5	32.8	22		N	46	1004.5	
18	Su	12.9	20.2	2.8			W	96	11:15	13.5	80		NW	31	1004.7	19.1	44		W	48	1011.0	
19	Mo	10.7	23.2	1.4			NW	65	13:08	15.5	82		NW	37	1013.1	21.4	59		WNW	39	1013.9	
20	Tu	13.0	18.9	1.4			SSE	52	15:42	14.1	53		S	28	1027.2	16.5	49		SSE	31	1029.5	
21	We	10.4	23.7	0			E	52	10:51	13.8	66		ESE	17	1029.0	22.6	44		E	31	1025.3	
22	Th	13.7	31.0	0			ENE	46	08:16	16.5	67		ENE	20	1024.4	30.3	29		N	24	1020.0	
23	Fr	14.4	31.4	0			N	50	11:51	20.3	52		NNE	22	1020.1	30.6	26		NNE	24	1015.4	
24	Sa	17.1	26.8	6.6			SW	39	03:12	17.6	95		NNE	20	1012.3	25.5	41		SW	15	1009.1	
25	Su	14.7	21.1	0.2			W	83	15:05	16.8	87		NW	30	1001.0	20.0	42		WNW	43	998.5	
26	Mo	7.6	17.7	8.4			W	70	05:05	13.3	70		WSW	37	1009.1	17.4	53		WSW	39	1011.9	
27	Tu	9.1	21.5	0			NNW	50	12:19	10.8	85		NNE	11	1015.8	20.5	41		NNW	28	1012.1	
28	We	10.8	22.6	0			WSW	52	12:35	18.1	48		NNW	17	1011.5	20.6	70		SSW	24	1014.3	
29	Th	13.2	22.4	0			WSW	48	14:46	14.8	73		NNW	13	1017.3	20.7	47		W	24	1015.3	
30	Fr	13.3	21.7	0			SW	52	13:57	15.3	86		NW	20	1015.9	19.6	63		SW	37	1017.3	
31	Sa	10.0	20.9	0			SW	39	13:33	12.2	88		N	9	1019.4	19.4	45		SSW	24	1016.7	
Statistics for March 2018																						
Mean		11.6	23.9							15.8	74			17	1018.1	22.4	46			27	1017.2	
Lowest		5.9	17.7							10.8	48		#	6	1001.0	16.5	13		ENE	9	998.5	
Highest		17.1	36.6	8.4			NW	104		22.0	97		#	37	1029.0	35.8	70		W	48	1029.5	
Total				23.0																		

Observations were drawn from Warrnambool Airport NDB (station 090186)

ICDJW3083 201803 Prepared at 13:01 UTC on 14 Apr 2018
Copyright © 2018 Bureau of Meteorology
Users of this product are deemed to have read the information and accepted the conditions described in the notes at <http://www.bom.gov.au/climate/dwo/ICDJW0000.pdf>

Mortlake, Victoria
March 2018 Daily Weather Observations



Date	Day	Temps		Rain mm	Evap mm	Sun hours	Max wind gust			9am						3pm						
		Min °C	Max °C				Dirn	Spd km/h	Time local	Temp °C	RH %	Cld eighths	Dirn	Spd km/h	MSLP hPa	Temp °C	RH %	Cld eighths	Dirn	Spd km/h	MSLP hPa	
							local	°C	%	eighths	km/h	hPa	°C	%	eighths	km/h	hPa					
1	Th	13.3	22.2	1.0			SSW	37	14.41	14.0	98		S	13	1018.1	21.0	56		SW	15	1017.7	
2	Fr	7.9	28.9	0			ENE	22	09.54	14.5	100		NE	9	1015.7	26.2	32		NE	7	1012.1	
3	Sa	11.6	24.6	0			SW	46	15.01	18.3	60		WNW	13	1008.7	23.1	50		WSW	28	1009.9	
4	Su	9.7	20.8	0			SW	35	13.36	13.1	100		Calm		1016.9	19.8	46		SSW	20	1016.8	
5	Mo	4.4	22.0	0			SSW	43	13.42	11.2	100		SSW	2	1020.3	19.6	41		S	20	1021.4	
6	Tu	5.1	25.1	0			S	37	15.18	14.8	80		SSE	17	1025.7	24.0	42		S	22	1024.0	
7	We	6.3	31.1	0			S	33	16.01	14.4	100		ENE	7	1025.9	30.1	26		SSW	6	1023.2	
8	Th	8.2	32.7	0			S	35	16.26	17.9	74		NNE	4	1024.8	31.9	23		S	15	1022.1	
9	Fr	9.3	34.9	0			SSW	37	15.46	18.1	75		NNE	2	1025.6	33.2	17		SSW	7	1022.7	
10	Sa	12.4	37.7	0			WNW	37	14.02	20.3	46		NNE	9	1023.7	35.8	12		W	17	1020.9	
11	Su	12.0	23.6	0			S	39	16.31	18.4	83		SSW	19	1024.1	20.6	54		S	22	1024.4	
12	Mo	13.5	20.4	0			SSW	41	13.41	15.2	68		SSW	15	1024.6	18.1	58		SSW	24	1023.6	
13	Tu	13.1	21.9	0			SSW	35	14.29	15.3	79		SSW	9	1024.2	20.7	46		SSW	20	1022.7	
14	We	13.0	22.9	0			SW	43	14.09	15.5	64		SSE	7	1021.1	22.0	43		SSW	15	1017.6	
15	Th	6.4	22.4	0			SW	31	16.22	10.6	95		W	4	1015.4	20.5	51		SSW	20	1015.3	
16	Fr	5.5	26.4	0			WNW	35	13.26	10.7	100		NE	6	1016.1	24.4	34		NNW	15	1012.5	
17	Sa	10.7	34.0	0			NW	104	20.08	19.9	60		N	17	1010.4	31.1	25		N	46	1005.7	
18	Su	12.5	21.1	0.4			WNW	76	11.28	13.0	81		WNW	35	1005.3	19.1	34		WSW	35	1011.0	
19	Mo	9.1	23.5	0.2			W	57	12.36	14.9	80		NW	30	1013.9	21.7	53		WNW	31	1013.9	
20	Tu	11.7	17.1	3.0			SSE	41	17.10	12.8	72		S	9	1027.0	15.3	53		SSE	28	1028.7	
21	We	8.2	23.1	0.2			E	59	09.16	14.9	68		E	30	1028.3	22.4	45		E	35	1025.0	
22	Th	13.1	30.8	0			E	50	00.25	15.2	73		ENE	15	1024.8	28.5	31		NNE	11	1020.7	
23	Fr	14.1	31.1	0			NNE	46	11.26	18.9	56		NNE	15	1020.8	30.0	27		NNE	26	1015.9	
24	Sa	16.7	28.0	13.4			W	44	04.08	17.3	100		NNE	7	1013.3	25.7	42		WNW	9	1009.1	
25	Su	15.2	22.6	0			W	85	15.26	16.5	89		NW	30	1001.5	21.0	35		WNW	44	999.2	
26	Mo	6.8	17.3	3.0			WSW	59	09.53	11.2	85		W	20	1009.0	15.7	65		W	22	1012.0	
27	Tu	6.0	22.2	0			N	35	10.52	9.1	98		NNE	6	1016.4	19.5	42		N	15	1012.5	
28	We	9.1	24.7	0			N	46	02.26	19.6	34		WNW	22	1011.6	24.0	51		WSW	15	1013.9	
29	Th	12.8	23.4	0			WSW	37	13.11	14.8	73		NW	7	1017.5	21.5	43		WSW	13	1015.0	
30	Fr	10.9	22.4	0			SW	43	10.23	14.6	92		WNW	13	1016.0	21.5	49		SW	26	1016.8	
31	Sa	6.3	22.6	0			SSW	24	16.11	10.2	100		N	4	1019.3	20.8	38		WNW	11	1016.4	
Statistics for March 2018																						
Mean		10.2	25.2							15.0	80			12	1018.3	23.5	40			20	1016.9	
Lowest		4.4	17.1							9.1	34			Calm	1001.5	15.3	12		SSW	6	999.2	
Highest		16.7	37.7	13.4			NW	104		20.3	100		WNW	35	1028.3	35.8	65		N	46	1028.7	
Total				21.2																		

Observations were drawn from Mortlake Racecourse (station 090176)

IDCJDW3053.201803 Prepared at 13:01 UTC on 14 Apr 2018
Copyright © 2018 Bureau of Meteorology
Users of this product are deemed to have read the information and accepted the conditions described in the notes at <http://www.bom.gov.au/climate/dwo/IDCJDW0000.pdf>